



4 additional Synthetic Fiber Feeding Systems plus a Knife Mill

5 Nit-Free Hammermills

3 Separate Powder or SAP Stations (feeding 5 individually controlled Forming Heads) + 1 additional Feeder

5 Synthetic Fiber Feeders - feeding any or all heads with the same, or different, chemistry and denier fibers (+ 2 extra low volume feeders for any forming head)